

## Uber Mic

**Latest Driver Version:** 1.0.2

**Release Date:** March 26, 2018

### Minimum System Requirements

- Windows 7 or later (32- or 64-bit) (This driver update is not necessary for macOS users.)
- Host USB 2.0 port

### Driver Update Instructions

1. Connect Uber Mic to your computer's USB port, and ensure Uber Mic and your computer are powered on.
2. Double-click the **Install M-Audio Uber Mic 1.0.2** file. You will then see a Windows prompt asking if you trust this application to make changes to your device. Select **Yes**. Wait for C++ to update (this may take several minutes).

Do **not** disconnect or power off Uber Mic or your computer until the update is completed.

**Note:** You will be asked to close applications that are using the Uber Mic driver or to restart your computer. Please save any of your work before making a selection.

3. Allow the update process to complete. When the update is completed, click **Finish**. You may need to restart your computer.

Congratulations—your Uber Mic is now using the latest driver!

### Change History

#### Changes Since 1.0.1

- Added lowest-available buffer setting to further reduce latency.
- Updated control panel icon.
- Minor bug fixes.

### Technical Support

For additional help, visit [m-audio.com/support](https://m-audio.com/support)